


# 福州新福兴玻璃有限公司



扫描全能王 创建

## 一、自行监测方案的调整情况

我司自行监测方案系于2020年9月为配合环保督察，监测结果只统计目前新方案要求数据（本方案目前没有调整）。

## 二、2022年自行监测结果统计

2022年自行监测结果统计见表1。

表1 2022年自行监测结果统计

监测站名称		监测因子		监测频次		监测方法		监测结果	
站名	地址	因子	单位	频次	方法	标准	结果	是否达标	备注
1									
2									
3									
4									
5									
6									
7									
8									
9									
10									
11									
12									
13									
14									
15									
16									
17									
18									
19									
20									
21									
22									
23									
24									
25									
26									
27									
28									
29									
30									
31									
32									
33									
34									
35									
36									
37									
38									
39									
40									
41									
42									
43									
44									
45									
46									
47									
48									
49									
50									
51									
52									
53									
54									
55									
56									
57									
58									
59									
60									
61									
62									
63									
64									
65									
66									
67									
68									
69									
70									
71									
72									
73									
74									
75									
76									
77									
78									
79									
80									
81									
82									
83									
84									
85									
86									
87									
88									
89									
90									
91									
92									
93									
94									
95									
96									
97									
98									
99									
100									



表2 2022年噪声监测情况统计

监测点	监测日期	检测结果 dB(A)	标准限值	是否达标
东侧厂界外 1m	2022.1.9	58.0	48.5	是
	2022.4.1	58.9	47.9	是
	2022.7.4	57.0	47.3	是
	2022.11.22	58.9	48.1	是
西侧厂界外 1m	2022.1.9	59.0	48.2	是
	2022.4.1	57.7	46.8	是
	2022.7.4	57.2	47.6	是

表3 2022年废气监测情况统计

监测点	监测日期	检测结果	标准限值	是否达标
废气	2022.11.22	1.79	100	是



